

## TOTALINE® TOOL ACCESSORIES



### Gas Valve Pressure Adapter P920-A611

Use for checking gas pressure on gas valve where the inlet gas is in a tight or hard to reach location. Can be used with any Totaline digital manometer.



### Optional K-Type Probes

#### Temperature Probe P920-CK20M

Pipe clamp probe for smaller diameter pipes-58° to 212°F (-50° to 100°C)



#### Temperature Probe P920-CK21M

K-type thermocouple pipe clamp for pipe diameters up to 1.2" and temp. up to 212°F. -58° to 212°F (-50° to 100°C)



#### Temperature Probe P920-GK13M

Teflon coated temperature probe. Measure temperatures up to 500°F. Use to measure temperature rise. -40° to 500°F (-40° to 260°C)



#### Silicone Tubing P920-A774

6 Foot length of Silicone tubing for Pressure measurements. Very flexible and will not go hard in in cold temperatures.



#### Universal T Fitting P920-A605

Ideal for use on setting pressure switches.



#### Test Leads P920-A080

UL Listed



#### Test Lead Kit P920-TLS10

Includes:  
A052 Adapters  
A057 Back Probes  
A067 Grabbers